




6190 chair




MATERIAL

Painted galvanised steel



6195 cushion




MATERIAL

Heat-formed polyurethane upholstered in a fabric containing laser-cut, water-repellent recycled material with the lower side coated in a non-slip rubberised effect.




EN 1022:2005	Level reached
EN 1728:2012+AC2013	Compliant level reached
6.4	L1
6.5	L1
6.6	L1
6.15	L1
6.16	L1
6.17	L1
6.20	L1
6.25	L1
6.27	L1




6190	1	10.0	0.166	58X56X82
6195	1	0.5	0.003	35X36X3

6191
armchair




MATERIAL

Painted galvanised steel




6195
cushion



MATERIAL

Heat-formed polyurethane upholstered in a fabric containing laser-cut, water-repellent recycled material with the lower side coated in a non-slip rubberised effect.



6191	1	11.0	0.277	58X57X84
6195	1	0.5	0.003	35X36X3

EN 1022:2005	Level reached
EN 1728:2012+AC2013	Compliant level reached
6.4	L1
6.5	L1
6.6	L1
6.10	L1
6.11	L1
6.15	L1
6.16	L1
6.17	L1
6.20	L1
6.25	L1
6.26	L1
6.27	L1